



---

## Maintaining a clean KonCote acrylic surface, application and other important information

---

### Maintenance for Periodic Cleaning

Using a high-pressure nozzle, KonCote applications should be sprayed off with water. This helps to prevent the surface from absorption of various stains.

Scrubbing with a brush and a mild detergent will help on the more difficult stains that may occur. Remember, applied applications are not self cleaning. Always keep surface clean, in return your investment stays protected.

### Removing Commonly known stains

#### Rust Stains

Naval jelly is recommended for removing rust, available from any grocery or hardware store.

#### Calcium Deposits

A whitish stain found in areas where water puddles occur. Remove by using Lime Away, available at any grocery store. Scrub areas thoroughly, allow to sit for 10 minutes, then rinse completely to remove any remaining residue.

#### Algae stains

Also caused by water puddles, stains that are green, red or black in color. Remove with a 50-50 mixture of cool chlorine water. Allow mixture to sit for 10-20 minutes. Scrub if needed, then hose surface off completely.

#### Paint/Acid

Can be touched up with KonCote sealer. Touch up clean and dry surfaces as you would water base paint. Also, the stained surface can be liquefied with the use of lacquer thinner.